

24/September/2021
 KYOCERA Corporation
 Head Office 6 takeda Tobadono-cho,
 Fushimi-ku Kyoto 612-8501 Japan
 Tel :+81-75-604-3500
 Fax:+81-75-604-3501
<https://global.kyocera.com/>

Declaration of Non-Use of TSCA

We hereby guarantee that the parts specified in 2) are in compliance with Article 6 (h) of TSCA .


This declaration applies only to parts itself specified in 2), and does not apply to parts which is not specified in 2), such as packing materials.

1) Substances concerned in Article 6 (h) of TSCA

abbreviation	Chemical name	CAS No.	Main application	threshold	Start of regulation
decaBDE	Decabromodiphenyl ether	1163-19-5	Flame retardants for electronic and communication equipment, fabrics, etc	No	2022/1/6
6PIP (3:1)	Phenol, isopropylated phosphate (3:1)	68937-41-7	Plasticizers, flame retardants, wear-resistant additives, etc.	No	2021/3/8
2,4,6-TTBP	2,4,6-Tris(tert-butyl)phenol	732-26-3	Fuel and fuel-related additives, oils and lubricants	0.3wt%	2026/1/6
PCTP	Pentachlorothiophenol	133-49-3	Used for rubber softening purposes.	1.0wt%	2022/1/6
HCBD	Hexachlorobutadiene	87-68-3	Solvent	No	2021/3/8

2) Products

Please refer to the list on the page(s) below.



Koji Yamane
 Manager of Electronic Components Quality Assurance Department
 Connector Products Quality Assurance Department
 KYOCERA Corporation

6806 Series

046806080103846+	046806050103846+	046806064108846+
046806030100846+	046806050103846+T	046806068108846+
046806040100846+	046806051000846+	046806070108846+
046806074000846+T	046806051000846+T	046806080108846+
046806080100846+	046806051103846+	
046806640000846+	046806051103846+T	
046806008000846+	046806060000846+	
046806008000846+T	046806060000846+T	
046806008103846+	046806060103846+	
046806008103846+T	046806060103846+T	
046806010000846+	046806064000846+	
046806010000846+T	046806064000846+T	
046806010103846+	046806064103846+	
046806010103846+T	046806064103846+T	
046806012000846+	046806068000846+	
046806012000846+T	046806068000846+T	
046806012103846+	046806068103846+	
046806012103846+T	046806068103846+T	
046806014000846+	046806070000846+	
046806014000846+T	046806070000846+T	
046806014103846+	046806070103846+	
046806014103846+T	046806070103846+T	
046806020000846+	046806080000846+	
046806020000846+T	046806080000846+T	
046806020103846+	046806080103846+T	
046806020103846+T	046806008108846+T	
046806021000846+	046806010108846+T	
046806021000846+T	046806012108846+T	
046806021103846+	046806014108846+T	
046806021103846+T	046806020108846+T	
046806026000846+	046806021108846+T	
046806026000846+T	046806026108846+T	
046806026103846+	046806030108846+T	
046806026103846+T	046806035108846+T	
046806030000846+	046806040108846+T	
046806030000846+T	046806041108846+T	
046806030103846+	046806045108846+T	
046806030103846+T	046806050108846+T	
046806035000846+	046806051108846+T	
046806035000846+T	046806060108846+T	
046806035103846+	046806064108846+T	
046806035103846+T	046806068108846+T	
046806036000800+	046806070108846+T	
046806040000800+	046806080108846+T	
046806040000846+	046806008108846+	
046806040000846+T	046806010108846+	
046806040103846+	046806012108846+	
046806040103846+T	046806014108846+	
046806041000846+	046806020108846+	
046806041000846+T	046806021108846+	
046806041103846+	046806026108846+	
046806041103846+T	046806030108846+	
046806045000846+	046806035108846+	
046806045000846+T	046806040108846+	
046806045103846+	046806041108846+	
046806045103846+T	046806045108846+	
046806050000800+	046806050108846+	
046806050000846+	046806051108846+	
046806050000846+T	046806060108846+	